

National Workshop on Importance of Disaster Risk Reduction and Resilience

Mizoram University, 10 April 2023

Recent Advances in Geotechnical Engineering Learning through Case Studies

Dr. Arindam Dey Associate Professor Geotechnical Engineering Division Department of Civil Engineering Center for Disaster Management and Research (CDMR) IIT Guwahati



11-04-2023

Hillslope Profiling at NEEPCO Hydel Plant, Saiphum, Mizoram Geophysical Prospecting – Crosshole Survey



THEORY v/s PRACTICE



Theory vs Practice: Tuirial Project, Mizoram

- Location of site: Tuirial, Saiphum, Mizoram
- Client: NEEPCO
- **Project**: Diversion of Tuirial River, Construction of dam and reservoir, Development of Hydro-Electric Power Plant
- **Calamity**: Seismic failure of a large hill-slope geopardizing the power-distribution unit located at the same foot-hill
- **Background information**: GSI report states only about static stability of the slope, no dynamic analysis
- **Objective**: Geophysical prospecting of the subsurface
- **Hindrance**: The site slope is already subjected to stabilization, so no scope/chance of getting soil samples
- Tests conducted: Seismic Crosshole Survey and MASW









Tuirial Project, Mizoram







6









Tuirial Project, Mizoram



11-04-2023

8

Instruments



11-04-2023

IDRRR, MZU, 2023

Instruments

- Ballard Shock Wave Generator
- 5D Geophone Receiver array
 - * 1 Vertical and 4 Horizontal









11-04-2023

10

Geological Investigation Report from GSI





Geophysical Prospecting

• Identification of the subsurface information through the applications of wave propagation through soil/rock media

Seismic Borehole Surveys



11-04-2023

IDRRR, MZU, 2023

13





Expectation vs Reality

- Multidirectional sensors in ideal ground
 - Each sensor should record the effect of the desired wave
- Heterogeneity in the soil creates record adulteration
 - Reflection from boundary and soil interface







13

11-04-2023

14

Signals: Theoretical and Field Observation





15

Arrival of S-wave

- Concept of Polarity Reversal
 - P-wave particle movement are in the same polarity independent of the direction of Ballard strike
 - S-wave particle movement changes the polarity depending on the direction of Ballard strike



11-04-2023

16

Signals: Theoretical and Field Observation





17

Arrival of S-wave



11-04-2023

18

Subsurface Velocity Profile



11-04-2023

19

Landslide at Calcom Cement Plant, Umrangso, Assam Forensic Geotechnology



Why is it important to conduct exploratory borings at **PROPER LOCATION**???



20

General Site Conditions

- Lat: *N*25°31′04″, Long: *E*92°47′19.3″, Elevation: +501m MSL
- Climatic conditions: Average Annual Rainfall 1672 mm (high)



11-04-2023

Pre-Reconnaissance Round-Table Discussion

- 2nd November 2015: Meeting with the client
 - * Pictures of damages of the 24-Colony Residential Housing blocks
 - 2 rows of 12 quarters face-to-face: All extensively damaged
 - Wall and Floor cracking / See through cracks
 - Detachment of plasters
 - Abnormal sounds from cracking
 - Detachment in floors
 - Shifting of soil in plinth raft













11-04-2023

22

Pre-Reconnaissance Round-Table Discussion

- 2nd November 2015: Meeting with the client, Dalmia Cements
 - * Pictures of damages in the protective retaining and boundary walls
 - Development of gaps and cracks in the retaining walls
 - Retaining wall 1: Between cement factory (workshop) and 24-Colony
 - Retaining Wall 3: Beside RCL road in front of 24 colony
 - Retaining wall 2: Frontal protection of 24-Colony (3 m)
 - Gaps in old boundary wall
 - Dislodgment of pavement and drains





• 2nd November 2015: Meeting with the client, Dalmia Cements

Contour map of the site





2nd November 2015: Meeting with the client, Dalmia Cements
Rough sketch of site topography





Site Visit for Reconnaissance Survey: 3rd Nov 2015





25







Site Visit for Reconnaissance Survey: 3rd Nov 2015





26







Site Visit for Reconnaissance Survey: 3rd Nov 2015







Site Visit for Reconnaissance Survey: 3rd Nov 2015



- Immense mass movement of soil
- Broken boundary wall
- Ejection of seeping water
- Overtopping of retaining wall
- Breakage of downhill protection wall



28



Extensive damage in the 24-Colony leading to relocation of workers

11-04-2023

29

Collection of Information and Data

• Geotechnical Investigation locations at the site





30

Collection of Information and Data

• Borehole locations at the site

* No boreholes present exactly at the failure site







32

Measurement and Monitoring

Displacement monitoring stations – 19 locations
Till December 2015





33

Measurement and Monitoring

• Typical lateral and vertical displacement monitoring data

* Some monitoring points were destroyed due to extreme displacement

| MONITORING REPORT OF EARTH DISPLACEMENT BEHIND STORE | | | | | | | | | | | | | | | | |
|--|----------------|------------------------------------|----------|--------|-------------|-----------------|----------|-----------|----------|--------------------|-----------------|----------|-----------|---------|----------|--------|
| AND WORK SHOP | | | | | | | | | | | | | | | | |
| SI NO | ARFA | BASE COORDINATE AND LVL 28/10/2015 | | | | 12-09-2015 | | | | | 12-11-2015 | | | | | |
| | | | | | | READING TAKEN | | DIFFRENCE | | SITE READING TAKEN | | | DIFFRENCE | | | |
| | | EASTING | NORTHING | RL | STN | NORTHING | RL | EASTING | NORTHING | RL | EASTING | NORTHING | RL | EASTING | NORTHING | RL |
| 11 | | 189.804 | 143.763 | 78.975 | POINT NO-11 | 143.786 | 78.64 | -1.216 | -0.023 | 0.335 | 191.021 | 143.798 | 78.591 | -1.217 | -0.035 | 0.384 |
| | | | | | | | | | | | | | | | | |
| 12 | REHAB QTRS | 191.629 | 137.583 | 77.403 | POINT NO-12 | 137.522 | 77.184 | -0.602 | 0.061 | 0.219 | 192.235 | 137.538 | 77.179 | -0.606 | 0.045 | 0.224 |
| | | | | | | | | | | | | | | | | |
| 13 | 24 COLONY | 251.861 | 167.28 | 67.727 | POINT NO-13 | 166.988 | 67.473 | -1.777 | 0.292 | 0.254 | 253.671 | 166.976 | 67.441 | -1.81 | 0.304 | 0.286 |
| 14 | | 245.488 | 139.819 | 68.046 | POINT NO-14 | POINT DESTROYED | | | | | POINT DESTROYED | | | | | |
| 15 | | 247.749 | 127.621 | 67.319 | POINT NO-15 | 127.129 | 66.94 | -1.609 | 0.492 | 0.379 | 249.421 | 127.108 | 66.831 | -1.672 | 0.513 | 0.488 |
| 16 | | 241.257 | 119.051 | 67.986 | POINT NO-16 | BOINT DESTROYED | | | | | | | | | | |
| 17 | | 238.211 | 108.001 | 69.271 | POINT NO-17 | | FOINT DI | SIKUTED | | | POINT DESTRUTED | | | | | |
| 18 | | 233.373 | 124.629 | 71.882 | POINT NO-18 | 124.816 | 70.604 | 0.012 | -0.187 | 1.278 | 233.358 | 124.821 | 70.588 | 0.015 | -0.192 | 1.294 |
| 19 | | 232.621 | 130.84 | 70.441 | POINT NO-19 | 130.662 | 68.995 | -1.268 | 0.178 | 1.446 | 233.897 | 130.65 | 68.965 | -1.276 | 0.190 | 1.476 |
| 20 | DRAIN ALONG | 151.875 | 152.097 | 86.317 | POINT 8A | 152.097 | 86.317 | 0.001 | 0 | 0 | 151.876 | 152.095 | 86.316 | -0.001 | 0.002 | 0.001 |
| 21 | RCL ROAD | 153.562 | 165.089 | 86.679 | POINT 9A | 165.089 | 86.68 | 0 | 0 | -0.001 | 153.561 | 165.087 | 86.68 | 0.001 | 0.002 | -0.001 |
| 22 | NALA BEHIND 24 | 262.832 | 119.858 | 53.89 | POINT NO-20 | 119.858 | 53.889 | -0.001 | 0 | 0.001 | 262.831 | 119.859 | 53.88 | 0.001 | -0.001 | 0.01 |
| 23 | COLONY | 277.088 | 136.566 | 49.881 | POINT NO-21 | 136.566 | 49.881 | -0.001 | 0 | 0 | 277.089 | 136.567 | 49.88 | -0.001 | -0.001 | 0.001 |



11-04-2023

35

Deciphering Chronological Events

• Contour and Profile of failure site

Sequence of construction of protection retaining walls





36

Deciphering Chronological Events

• Hillslope topography along different sections




37

- Forensic study of hillslope failure using Geostudio
 - * Soil layering done on the basis of nearby borehole stratigraphies
 - Depth of water table Unknown





Preliminary Models and Failure Analysis

• Forensic study of hillslope failure

* Material properties used in the model for the numerical simulation

| Material properties of the Primary model PM | | | | | | | | | | |
|---|----------------------------------|-----------------|------------|--------------------------------|-----------|-------------|--------------------------------|--|--|--|
| Layer | Undrained Strength Parameters | | | Drained Strength Parameters | | | Unit | Saturated | Saturated volumetric | |
| | c _u (kPa) | φ_u (°) | E (MPa) | c' (kPa) | φ' (°) | E' (MPa) | weight (kN/m ³) | permeability K _{sat} (m/s) | water content Θ_{sat} (m^3/m^3) | |
| Soil layer I | 18.5 | 4 | 4.7 | 12.33 | 4 | 4.2 | 19 | 3x10 ⁻⁸ | 0.425 | |
| Soil layer II | 18.5 | 4 | 4.7 | 12.33 | 4 | 4.2 | 19 | 3x10 ⁻⁸ | 0.425 | |
| Soil layer III | 18.5 | 4 | 4.7 | 12.33 | 4 | 4.2 | 19 | 3x10 ⁻⁸ | 0.425 | |
| Rock | - | - | 683 | - | - | 610.4 | 24.1 | $2x10^{-10}$ | 0.087 | |
| Retaining wall | - | - | 17000 | - | - | 15194 | 29 | 3x10 ⁻¹³ | 0.33 | |

| Material properties of the tertiary model TM | | | | | | | | | | |
|--|-------------------------------------|-------------|-------|--------------------------------|------------|-------|----------------|---------------------------|----------------------------------|--|
| Layer | Undrained Strength Parameters | | | Drained Strength Parameters | | | Unit weight | Saturated Permeability | Saturated Volumetric water | |
| | C_{u} | φ_u | Ε | с' | φ' | E' | (kN/m^3) | K_{sat} (m/s) | content Θ_{sat} | |
| | (kPa) | (°) | (MPa) | (kPa) | (°) | (MPa) | | | (m^{3}/m^{3}) | |
| Soil layer I | 18.5 | 4 | 4.7 | 12.33 | 4 | 4.2 | 19 | 3x10 ⁻⁸ | 0.425 | |
| Soil layer II | 94 4 90.65 | | 90.65 | 62.66 | 4 | 81 | 19 | 3x10 ⁻⁸ | 0.425 | |
| Soil layer III | 94 | 4 | 90.65 | 62.66 | 4 | 81 | 19 | 3x10 ⁻⁸ | 0.425 | |
| Rock | - | - | 683 | - | - | 610.4 | 24.1 | $2x10^{-10}$ | 0.087 | |
| Retaining wall | - | - | 17000 | - | - | 15194 | 29 | 3x10 ⁻¹³ | 0.33 | |

| Material properties of the secondary model SM | | | | | | | | | | | |
|---|-------------------------------------|-------------|------------|--------------------------------|-----------|-------------|----------------|---------------------------|---|--|--|
| Layer | Undrained Strength Parameters | | | Drained Strength Parameters | | | Unit weight | Saturated Permeability | Saturated Volumetric water | | |
| | c_u (kPa) | φ_u | E (MPa) | c' (kPa) | φ' (°) | E' (MPa) | (kN/m^3) | K_{sat} (m/s) | content Θ_{sat} (m ³ /m ³) | | |
| Soil layer I | 18.5 | 4 | 4.7 | 12.33 | 4 | 4.2 | 19 | 3x10 ⁻⁸ | 0.425 | | |
| Soil layer II | 18.5 | 4 | 4.7 | 12.33 | 4 | 4.2 | 19 | 3x10 ⁻⁸ | 0.425 | | |
| Soil layer III | 94 | 4 | 90.65 | 62.66 | 4 | 81 | 19 | 3x10 ⁻⁸ | 0.425 | | |
| Rock | - | - | 683 | - | - | 610.4 | 24.1 | $2x10^{-10}$ | 0.087 | | |
| Retaining wall | - | - | 17000 | - | - | 15194 | 29 | 3x10 ⁻¹³ | 0.33 | | |

38





39

Schematic Section of Retaining Walls





- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - **Stage 1**: In-situ analysis to assess the stability of the virgin slope before human intervention





- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 2: Excavation of foundation of building





Preliminary Models and Failure Analysis

• Forensic analysis of hillslope failure

- * Sequential anthropogenic intervention at the site (Stages of construction)
 - **Stage 3**: Imposition of building load at the site due to the construction of the building (Calculated from structural data)





Preliminary Models and Failure Analysis

• Forensic analysis of hillslope failure

- * Sequential anthropogenic intervention at the site (Stages of construction)
 - **Stage 4**: Filling back and embedment of the shallow footings (Stages 3 and 4 are done simultaneously in the field)





- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 5: Excavation of the foundation of the retaining wall R1





45

- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 6: Construction of R1 and simultaneous back-filing





46

- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 7: Excavation of the foundation of the retaining wall R2





- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 8: Construction of R2 and simultaneous back-filing





48

- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 9: Excavation of the foundation of the retaining wall R3





- Forensic analysis of hillslope failure
 - * Sequential anthropogenic intervention at the site (Stages of construction)
 - Stage 10: Construction of R3 and simultaneous back-filing





Preliminary Models and Failure Analysis

- Forensic analysis of hillslope failure
 - * Application of Parent-Child concept to amalgamate various modules
 - SEEP/W \rightarrow SIGMA/W \rightarrow SLOPE/W (Applied in sequence)
 - SEEP/W → Finite element based steady-state seepage analysis to generate the pore-water pressures under a given WT
 - → FE-based transient seepage analysis to identify the steady state WT due to a rainfall based infiltration and development of transient pore-water pressures

50

- SIGMA/W → Finite element based load-deformation analysis conducted by incorporating the steady-state WT and pore-water pressures generated from the preceding SEEP/W analysis
- SLOPE/W → Limit Equilibrium based slope stability analysis to identify the critical slip surface and the Factor of Safety values, by incorporating the results from the preceding SIGMA/W analysis



SI

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





52

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





53

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





54

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





55

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





56

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition





Preliminary Models and Failure Analysis

- Slope stability analysis using Slope/W
 - * Morgenstern-Price Method for analysis
 - Entry-Exit method for slip surface definition

Retaining walls and backfills simply kept on adding weight to the system leading to more destabilization

58





Preliminary Models and Failure Analysis

- Slope stability analysis using Slope/W
 - Morgenstern-Price Method for analysis

This did not happen in the field, RW4 was overtopped by mud and water \rightarrow Necessity for further investigation

59

Entry-Exit method for slip surface definition







Preliminary Models and Failure Analysis

• Identification of the most feasible soil stratigraphy

Sased on stability analysis of various stages (Slope/W Module)

• PM and SM fails under the presence of any WT condition even in the in-situ condition (landslide in natural hillslope was not recognized at site)

| Stage of construction | Dry | Vater level at a depth of 1 m (W1) | Water level at a depth of 4 m (W2) | Water level at a depth of 8 m (W3) | t n | Stage of construction | Dry | Water level at a depth of 1 m (W1) | Water level at a depth of 4 m (W2) | Water level at a depth of 8 m (W3) |
|-----------------------|-------|--|--|--|--------|-----------------------|-------|--|--|--|
| Primary Model (PM) | | | | | | | Seco | ndary Model (SM) | | |
| (1) | 1.106 | 0.693 | 0.765 | 0.821 | _ | (1) | 1.416 | 0.920 | 1.029 | 1.054 |
| (2) | 1.156 | 0.882 | 0.886 | 0.919 | | (2) | 1.388 | 0.952 | 1.025 | 1.053 |
| (3) | 0.928 | 0.692 | 0.694 | 0.717 | | (3) | 1.038 | 0.489 | 0.609 | 0.854 |
| (4) | 0.937 | 0.765 | 0.736 | 0.778 | | (4) | 1.078 | 0.975 | 0.976 | 0.88 |
| (5) | 0.947 | 0.777 | 0.750 | 0.792 | | (5) | 1.076 | 0.989 | 0.975 | 0.875 |
| (6) | 0.930 | 0.765 | 0.736 | 0.778 | | (6) | 1.064 | 1.038 | 1.038 | 0.919 |
| (7) | 0.928 | 0.764 | 0.743 | 0.776 | | (7) | 1.087 | 1.146 | 1.077 | 0.935 |
| (8) | 0.929 | 0.764 | 0.744 | 0.777 | | (8) | 1.083 | 1.151 | 1.097 | 0.936 |
| (9) | 0.940 | 0.77 | 0.758 | 0.779 | | (9) | 1.071 | 1.080 | 1.083 | 0.931 |
| (10) | 0.928 | 0.764 | 0.744 | 0.777 | | (10) | 1.081 | 1.066 | 1.060 | 0.924 |

| Stage of construction | Dry | Water level at a depth of 1 m (W1) | Water level at a depth of 4 m (W2) | Water level at a depth of 8 m (W3) | |
|-----------------------|-------|--|--|--|--|
| | Terti | ary Model (TM) | | | |
| (1) | 2.112 | 1.411 | 1.588 | 1.511 | |
| (2) | 0.976 | 0.821 | 0.793 | 0.769 | |
| (4) | 0.967 | 0.850 | 0.802 | 0.774 | |
| (5) | 0.985 | 0.875 | 0.825 | 0.805 | |
| (7) | 1.373 | 0.817 | 1.065 | 1.025 | |
| (8) | 1.344 | 0.752 | 0.967 | 1.007 | |
| (10) | 1.294 | 1.024 | 0.984 | 0.959 | |

Tertiary model indicates that imposition of building load (Stage 3) induced the marginal stability in the natural hillslope



61

- Influence of WT depth on the Tertiary Model
 - * Attempt to identify the location of the Water Table
 - In dry condition, the imposition of building load (Stage 3) might have initiated some creep instability, which was arrested by constructed RWs
 - WT assumed at any depth (W1, W2 or W3) showed similar instability after Stage 3
 - However, under such scenarios, no water seepage is expected in the hillslope
 - The possible location of initial WT yet remains unsolved from this aspect

| | Stage of construction | Dry | Wat | ter level at a pth of 1 m (W1) | Water level at a depth of 4 m (W2) | Water level at a depth of 8 m (W3) |
|--|--|--|-----|--|--|--|
| | | Tertiary Model (TM) | | | | |
| Building Load Soil Layer II Soil Layer II Bedrock 5 m 240 m | (1) (2) (3) (4) (5) (6) (6) (7) (8) (9) (10) | 2.112 2.100 0.976 0.967 1.015 0.985 1.373 1.344 1.288 1.294 | | 1.411 1.373 0.821 0.850 0.875 0.838 0.817 0.752 1.029 1.024 | 1.588 1.577 0.793 0.802 0.825 0.798 1.065 0.967 1.035 0.984 | 1.511 1.513 0.769 0.774 0.805 0.785 1.025 1.007 0.975 0.959 |



11-04-2023

63

- What happened to water seeping out from slope face behind the 24 colony → Question still looms !
- Inclusion of rainfall and rainwater infiltration in the SEEP/W analysis
 - ✤ Prevalent infiltration during the monsoons 5.4 x 10⁻⁸ m/s (estimated from climatic and meteorological data)
 - * Modeled as constant head of water over the entire slope





64

- Interesting inferences !!!
 - ✤ Infiltration leads to the rise of the WT
 - WT, upon rising, intersects the slope face near the 24 colony





65

- Interesting inferences !!!
 - * Intersection of WT at the slope face near the 24 colony (160-180 m from left)
 - Denoted by achievement of zero or negative water flux at the slope face
 - Water comes out of the slope face at the prescribed location
 - Time duration of the rise of WT to intersect: Approximately 3-6 h of rain
 - Coincidentally, the same was reported from the field that the first slide behind the colony was noted after an initial 3-4 hr of rainfall around October 2015





66

- Interesting inferences !!!
 - *Intersection of WT at the slope face near the 24 colony (160-180 m from left)*
 - Field observation of water emanating out of the slope face behind 24 colony



11-04-2023

18

IDRRR, MZU, 2023

Preliminary Models and Failure Analysis

• Still, we were unhappy !!! ⊗

Why so less displacement behind the 24 colony, while the field displacement was maximum at that location !?

• Max displacement around building???



61



11-04-2023

Model Updating from Further Field Studies

- What did we miss earlier???
 - Is it the boreholes and stratigraphy??
 - Yes !! They were not really from failure site
 - It is possible that our assumption of soil stratigraphy and even some of the soil parameters are incorrect ⁽²⁾

* Prescription

- Conduct few more borehole surveys at the landslide site itself
 - Site was accessible? Yes !!



68

11-04-2023

69

- A new understanding of the failure site
 - * Presence of thick cover of loosely deposited fill soil
 - Deposited during construction of workshop and store
 - This information was completely missing in earlier discussions





70

- A new understanding of the failure site
 - * Presence of shale pockets
 - Offers shear surface when get wet due to infiltration and percolation of water





- A new understanding of the failure site
 - Presence of weathered rock/stone
 - Allows easy gradient-based migration of water beneath the slope surface





72

- A new understanding of the failure site
 - * Presence of thick deposit of shale
 - May act either as bedrock when dry, or offer sliding surface when wet


11-04-2023

73

Model Updating from Further Field Studies

- A new understanding of the failure site
 - * A strong intuition developed that the failure is actually shallow slide due to the movement of the loose deposit itself
 - All the retaining walls and workers colony were simply resting on the loose deposit





74

Model Updating from Further Field Studies

• A new numerical model is developed



11-04-2023

SIGMA

IDRRR, MZU, 2023

Model Updating from Further Field Studies

• Model parameters are chosen from the new set of experimental investigations (from both field and lab)

| | Layer | Type of soil | Material model (in Sigma/W) | Material model (in Slope/W) | Total paramete Dry | l stress er <u>su</u> (kPa) Saturated | E (MPa) | Unit weight (kN/m ³) |
|-----------|-------|---------------------------|-----------------------------------|-----------------------------------|--------------------------|---|------------|--|
| GMA/W and | 1 | Filling | Elastic plastic | Undrained $\phi = 0$ | 42 | 22 | 4.08 | 15 |
| SLOPE/W | 2 | Moderately stiff Shale | Linear Elastic | Impenetrable bedrock | - | - | 860 | 22 |
| | 3 | Weathered Rock | Linear Elastic | Impenetrable bedrock | - | - | 860 | 22 |
| | 4 | Hard Shale | Linear Elastic | Impenetrable bedrock | - | - | 860 | 22 |

| Layer | Type of soil | Material model (in SEEP/W) | Saturated hydraulic conductivity (m/sec) | Saturated volumetric water content (m ³ /m ³) obtained from porosity | |
|-------|---------------------------|-------------------------------|--|---|--------|
| 1 | Filling | Saturated Only | 3 × 10 ⁻⁸ | 0.425 | |
| 2 | Moderately stiff Shale | Saturated Only | 2 × 10 ⁻¹⁰ | 0.087 | SEEP/W |
| 3 | Weathered Rock | Saturated Only | 2 × 10 ⁻¹⁰ | 0.087 | |
| 4 | Hard Shale | Saturated Only | 2 × 10 ⁻¹⁰ | 0.087 | |



76

Results from Updated Analysis

• Application of various loads in stages (as earlier)





Displacement Results from Updated Analysis

- Application of colony load
 - Invokes sufficient displacement in saturated stage





78

Displacement Results from Updated Analysis

- Application of building load
 - * Another slip deformation zone is initiated





Displacement Results from Updated Analysis

• Application of RW1





80

Displacement Results from Updated Analysis

• Application of RW2

♦ *RW2* placed on loose deposit \rightarrow *Deformation zones start overlapping*





8

Displacement Results from Updated Analysis

- Application of RW3
 - RW3 placed on loose deposit \rightarrow Deformation zones completely overlaps
 - MASS MOVEMENT OF SOIL towards complete failure





82

Displacement Results from Updated Analysis

- Application of RW4
 - The bottommost barrier gets overtopped by excessively displacing soil



OUTCOME OF FORENSIC ANALYSIS

Happy to identify the background reasons of cause, triggers and subsequent failure

Matched well with the several observations made during field reconnaissance
 reconnaissance



84

Adopted Stabilization Scheme

- Cut-off Sheet Pile Wall with adequate drainage
 - * Sheet pile walls to be pushed and embedded in the weathered rock layer
 - 2-sheet pile row / 3-sheet pile row strategies





85

Adopted Stabilization Scheme

• Cut-off Sheet Pile Wall with adequate drainage

* A successful stabilization scheme was noted from stability analysis

| | | FoS | | | | | |
|-----------|--------------------------|-------------------------|--|--|--|--|--|
| SI. No | Stage of construction | Before Stabilization | | After Stabilization (3 rows of cutoff wall) | After Stabilization (2 rows of cutoff wall) | | |
| 1 | In-situ | 1.014 | | 2.212 | 1.589 | | |
| 2 | Colony Load | 0.970 | | 1.710 | 1.5 | | |
| 3 | Building load | 0.645 | | 2.244 | 1.615 | | |
| 4 | Construction R1 | 0.669 | | 2.205 | 1.611 | | |
| 5 | Construction of R2 | 0.669 | | 2.132 | 1.606 | | |
| 6 | Construction of R3 | 0.671 | | 2.249 | 1.641 | | |



- Cut-off Sheet Pile Wall with adequate drainage
 - * Large displacement behind the colony were well arrested



11-04-2023

87

Heritage Railway Station at Udaipur, Agartala, Tripura Construction in Very Difficult Subsoil



Ground Improvement Methodology



88

Project Walkthrough

- Udaipur railway station of Agartala-Sabroom New BG Line Project is situated between Km. 42.2 to 43.3 (Km. 0.00 at Agartala) in the state of Tripura.
- Station is situated in the Sukhsagar Lake of Udaipur.
 - Water logged and marshy soil.
 - Existence of soft soil (Silty Clay) up to 13.3-20 m depth at various locations.
 - Out of 13.3 m, top 8 m is mixed with decomposed trees & wooden logs.
- During construction of building differential settlement of piles.

11-04-2023

89

Rail Links of Tripura (Proposed and Existing)





Udaipur Railway 🖪

Sukhsagar

Lake

Planned Developments

- Railway station building and associated facilities
- Railway line over embankment
- Station Yard...

Uttar Chandrapu

Uttar Chandrapur Mosque Tripura Sundari Temple

90

Udaipur Station



91

Chronology of the Problem

- Formation in station yard:
 - ✤ Construction started in Dec '2010.
 - Excessive settlement in the range of 1-2 m was noticed in Oct' 2011 when constructed embankment height reached 3 m.
 - ✤ The work continued & reached to a height of 5 m.
 - Huge Settlement, Cracks and Heaving of adjacent ground beyond toe (up to 25m on both sides of embankment).
- Station building:
 - *Earth filling started in Nov* 2011.
 - ✤ Pile foundation started in Dec '2011.
 - ✤ Pile foundation completed by Nov'2012.
 - * Differential settlement observed in Pile cap No. 13, 14 and 35 in May 2012
 - Cracks noticed in plinth beam and grade beams connected to above mentioned pile caps.
 - * Brickwork for wall done in Jan' 2014 and differential settlement increased further.

11-04-2023

IDRRR, MZU, 2023

A 16.10











94

3-Stage Remedial Measures

- Ground improvement of the adjoining area by Pre-fabricated Vertical Drain (PVD) for accelerating consolidation of soft soil.
 Arresting long-term settlement
- Sheet piling of adequate retaining capacity around the station building before stripping off the existing surrounding embankment for PVD installation.

* Preventing the movement of embankment soil

• Retrofitting of the station building by providing additional pile raft system and Carbon Fibre Reinforced Polymer (CFRP).

* Distribution of building load and Strengthening the building



95

Embankments on Soft Soils

- Embankment constructions are required for highways, railways
 Lengths are in many kms
- Many times the foundation soils are found to be of soft soils
 - Low shear strength
 - May not have sufficient bearing capacity
 - * High compressibility
 - Undergo higher settlement
 - Resulting large differential settlements
- The design and construction of embankments over soft soil has always been a challenging task for engineers

Proper engineered attention required during initial planning stage with proper ground improvement techniques

11-04-2023

Problems Faced during Embankment Construction

- Height of embankment = 6.2 m
- Embankment construction started in stages: Dec' 2010.
 - September 2011
 - First failure noticed at 3.0-3.5 m height:
 - ***** *March* 2012
 - Large settlement of 5-5.2 m
 - Heaving up of ground until 30 m distance from the embankment
- After that further construction stopped



11-04-2023





98

Problem Description

• New broad gauge (BG) railway line project (about 110 km) railway embankments are being constructed



- * The site of interest is in a water logging area
- * During monsoon, the water level rises approx. to 3 4 m above the EGL
- * The old soil reports available for the site indicate that the subsoil consist of soft soils up to about 12-13 m below EGL.
- *Construction of the embankment was started during Dec 2010 directly on the natural soil without giving any pre-treatment.*

11-04-2023

99

Field Investigation



Locations of boreholes (CE Testing report, 2013)

11-04-2023

100

Boreholes along the railway line

-AGARTALA

SABROOM ---



11-04-2023

IDRRR, MZU, 2023



Stratification of the subsoil

| Stratum | SPT N-values | Depth (m) |
|-----------|--------------|-----------|
| Layer I | 3 - 5 | 4 |
| Layer II | 5 - 10 | 5 |
| Layer III | 10 - 15 | 4 |
| Layer IV | > 70 | 5 |





Tentative Subsurface Profiling

- From available bore log data of 5 boreholes, 4 different layers are identified.
- Depending on the SPT N-values, cohesion and physical appearance of the soil.







Investigations for Forensic Analysis

- New Borelogs in adjacent areas (outer embankment area)
- SPT
- SCPT
- UDS collection and Laboratory tests

11-04-2023

104

Boreholes at the outer side of embankment



11-04-2023

105

Boreholes at the outer side of embankment



11-04-2023

106

Typical SCPT results



Corr. Friction Resistance,fs, kg/sqcm



11-04-2023

107

Laboratory tests on Undisturbed Soil

- * Proper identification and classification of the sub-soil deposits is required.
- * Undisturbed samples of 100 mm dia. were collected by means of pushing Shelby tubes.
- * Index and Engineering properties of the soil were found out. / Wax Coat



Undisturbed sample cores obtained from the site location

Bore hole details

11-04-2023

108

Index Tests



a) Dry Sieve analysis, b) Hydrometer Analysis, c) Liquid Limit, d) Specific gravity by gravity bottles and e) Plastic Limit


109

Index Properties

• Summary of index properties and classification of cohesive soil samples

| Bore Hole | Sample Number | Depth (m) | Natural Moisture content, % | Specific Gravity | Liquid Limit | Plastic Limit |
|-----------|------------------|------------|-----------------------------------|---------------------|-----------------|------------------|
| BH 01 | UDS-02 | 1.65-2.10 | 28.57 | 2.511 | 42.6 | - |
| BH 03 | UDS-01 | 2.00-2.45 | 26.58 | 2.601 | - | 20 |
| BH 01 | UDS-04 | 5.25-5.70 | 82.52 | 1.398 | 55.2 | 19.04 |
| BH 04 | UDS-06 | 9.55-10.00 | 23.54 | 2.335 | 42.4 | 20.8 |
| BH 03 | UDS-04 | 6.25-6.70 | 40.29 | 2.725 | 47.6 | - |
| BH 05 | UDS-04 | 5.15-5.60 | 80 | 2.257 | 48.8 | - |

11-04-2023

Particle size Distribution

| Particle size | Layer I (%) | Layer II (%) | Layer III (%) |
|----------------------------|-------------|--------------|---------------|
| Coarse sand (4.75mm-2mm) | 0.5 | 2 | 0 |
| Medium sand (2mm-0.425mm) | 1.5 | 0 | 2 |
| Fine sand (0.425m-0.075mm) | 40 | 7 | 30 |
| Silt (0. 075mm-0.002mm) | 28 | 47 | 34 |
| Clay (<0.002mm) | 30 | 44 | 34 |

Both wet sieve and hydrometer analysis are conducted to complete particle size distribution of the sub-soil



Grain Size (mm)



Engineering Properties of soil

- Undrained shear strength of the soil is found out from Unconfined Compression test (UCS) and laboratory Vane shear test.
- * Compressibility and Permeability Parameters are found out from Oedometer test.



a) Vane Shear test b) Uniaxial compression test and c) Oedometer Test

11-04-2023

Undrained Shear Strength

| | | | UCS | | Vane Shear | | | |
|-----------|------------------|-------------|------------------------|----------------------|------------------------|----------------------|-------------|--|
| Bore Hole | Sample Number | Depth (m) | Moisture Content, % | c _u (kPa) | Moisture Content, % | c _u (kPa) | Consistency | |
| BH 01 | UDS-02 | 1.65-2.10 | 28.57 | 26.48 | 30.21 | 34.3 | Soft | |
| BH 01 | UDS-04 | 5.25-5.70 | 75.23 | 12.17 | 82.52 | 7.775 | Very Soft | |
| BH 01 | UDS-10 | 16.10-16.55 | - | 7.03 | - | - | Very Soft | |
| BH 03 | UDS-01 | 2.00-2.45 | 26.58 | 55.69 | | 16.01 | Very Soft | |
| вн оз | UDS-04 | 6.25-6.70 | 30.92 | 28.61 | 40.29 | 44.36 | Medium | |
| BH 04 | UDS-04 | 5.15-5.60 | - | - | 21.58 | 105.2 | Stiff | |
| BH 04 | UDS-06 | 9.55-10.00 | 27.67 | 41.87 | 23.54 | 53.97 | Medium | |
| BH 05 | UDS-02 | 1.50-1.95 | 15.16 | 54.11 | 20.36 | 25.61 | Stiff | |
| BH 05 | UDS-04 | 5.15-5.60 | - | - | 80 | 14.17 | Soft | |
| BH 05 | UDS-08 | 12.5-12.6 | 34.54 | 22.5 | 24.4 | 54.88 | Soft | |

Distribution of undrained shear strength is very erratic (mostly soft) – conducive of large differential settlements

11-04-2023

113



Modes of failure



Stress strain response of different layers under unconfined compression



Consolidation Tests

- Typical void ratio against effective stress for different layers of the soil are drawn from the readings of consolidation test.
- C_c and C_v values are calculated from the graphs.



| Borehole | Depth (m) | Moisture Content, w% | Initial Void Ratio, e _o | C _c | C _v (cm²/sec) | k _v (cm/sec) |
|----------|-----------------|-------------------------|---------------------------------------|----------------|--------------------------|-------------------------|
| UDS-04 | 10.65- 11.10 | 40.8 | 1.126 | 0.365 | 0.000576 | 1.57x10 ⁻⁰⁸ |
| UDS-03 | 9.0-9.45 | 61 | 1.702 | 0.664 | 0.001369 | 5.05x10 ⁻⁰⁸ |
| UDS-03 | 10.0-10.45 | 87.9 | 2.719 | 1.079 | 0.000838 | 6.04x10 ⁻⁰⁸ |

11-04-2023

115

Subsoil Parameters

| Stratum | Fill | Layer I | Layer II | Layer III | Layer IV |
|---|------|-----------------------|-----------------------|-----------------------|----------|
| Unit Weight (kN/m ³) | 19.5 | 17.5 | 18 | 18 | 19 |
| Specific Gravity | 2.45 | 2.2 | 2.34 | | - |
| Cohesion (kPa) | 30 | 7 | 15 | 25 | 0 |
| Angle of Internal Friction, ϕ ° | - | <u> </u> | - | | 32-35 |
| Natural Moisture content | 24% | 48% | 23.54% | 34.54% | - |
| Liquid Limit | 42% | 50% | 42.40% | - | - |
| Plastic Limit | 20% | 19% | 20.80% | - | - |
| Plasticity Index | 22% | 31% | 21.60% | - | - |
| Compression Index, C _c | - | 1.079 | 0.365 | 0.664 | - |
| Coefficient of Consolidation, C _v (cm ² /sec) | | 0.000838 | 0.000576 | 0.001369 | |
| Permeability (cm/sec), k _v | - | 8.76x10 ⁻⁹ | 1.57x10 ⁻⁸ | 5.05x10 ⁻⁸ | - |
| Initial void ratio, e _o | - | 2.719 | 1.126 | 1.702 | - |



116

Sub-soil Profile with properties

- The ultimate soil profile with parameters found out from the laboratory tests.
- These properties will be used in modeling in Settle3D software.

| Layer I | Υ _b = 17.5 kN/m³, C = 7 kPa | 4 m 🌔 | \uparrow |
|-----------|--|-------|------------|
| Layer II | Υ _b = 18 kN/m³, C = 15 kPa | 5 m | 13 m |
| Layer III | $Y_{\rm b} = 18 \text{ kN/m}^3$, C = 25 kPa | 4 m 🌔 | |
| Layer IV | <u>Υ_b = 19 <u>kN</u>/m³, φ = 32°-35°</u> | 5 m | |

Railway Embankment Resting on Soft Soil



118

Soil profile considered for the analysis





119

Analysis of Embankment stability

- Using SETTLE3D software (Rocscience 2014)
 - The primary consolidation settlement of 0.505 m, 0.755 m, and 0.951 m after 3.14 m, 4.64 m, and 6 m embankment heights were observed.



- Numerical study confirms large deformations observed in the field
- Warrants for ground improvement



Large Differential Settlements along the Embankment







121

Initial Recommendation

- Construction of widened embankment encompassing failed one
 - Having slope of 4.5:1 for 3.1 m height from GL and slope of 2.5:1 for rest 3.1m height of embankment with 26.5 m wider sub bank at 3.1m from top.
 - * Stage Construction with measurement settlement & pore pressure.
- Requirement of Additional land.
- Requirement of more time for stage construction
- Possibility of settlement of central embankment in future





122

Restoration of embankment

- Prefabricated vertical drains (PVDs) or sand piles with preloading
 - *Owing to the time constraint of the project and unavailability of stone aggregate nearby to the site*





123

Typical Schematic of Railway Embankment on PVD



































11-04-2023

CE 532: Lecture 1: Introductory Session

129



a) Laying of Coarse sand, b) Laying of Non-Woven Geo-textile, c) Laying of Granular Blanket.

d) Laying of Woven Geo-textile, e & f) Stage construction of embankment.

11-04-2023





131

Instrumentation





Piezometers & Settlement Gauges









11-04-2023

Construction Plan for Embankment at Udaipur

| Height of | P _{0,} | δΡ, | No of Days | Settlement | Cumulative | Time* | | Cumulative | |
|-----------|-----------------|------------|------------|-------------|-------------|---------|------|---------------|-------|
| embankm | kPa[H/2*6. | kPa | | due to load | Settlement, | period, | Uh | settlement, m | U |
| ent, m | 53] | [(∆h*19)+2 | | with time, | mm | days | | (achievable) | |
| | | 4] | | mm | | | | | |
| | | | | | | | | | |
| 0 | 43.26 | 0.00 | 0 | 0.00 | 0.00 | 0 | 0.00 | 0.00 | 0 |
| 0.5 | 43.26 | 33.50 | 20 | 0.488 | 0.488 | 20 | 0.45 | 0.22 | 17.75 |
| 1 | 43.26 | 43.00 | 20 | 0.099 | 0.587 | 40 | 0.70 | 0.42 | 33.71 |
| 1.5 | 43.26 | 52.50 | 20 | 0.089 | 0.676 | 60 | 0.84 | 0.56 | 45.37 |
| 2 | 43.26 | 62.00 | 20 | 0.081 | 0.756 | 80 | 0.91 | 0.69 | 55.67 |
| 2.5 | 43.26 | 71.50 | 20 | 0.074 | 0.831 | 100 | 0.95 | 0.79 | 63.76 |
| 6.2 | 43.26 | 141.80 | | 0.407 | 1.238 | ** | | | |

Considering 20 days of time period after execution of each stage of 0.5m height.

| Height of embankment (m) | No of Days | Corresponding degree of consolidation | Initial Cohesi on (kPa) | Increased pressure δP [due to DL (kPa) | Gain in Cohesion value | Final Cohesion , kPa | Bearing Capacity of soil, in kN/m ² |
|--------------------------------|---------------|---|----------------------------------|---|------------------------------|----------------------------|---|
| 0 | 0 | 0 | 4 | 0 | 0 | 4 | 20.6 |
| 0.5 | 20 | 45 | 4 | 9.5 | 0.75 | 4.75 | 24.4 |
| 1 | 20 | 71 | 4 | 19 | 2.38 | 6.38 | 32.8 |
| 1.5 | 20 | 83 | 4 | 28.5 | 4.18 | 8.18 | 42 |
| 2 | 20 | 91 | 4 | 38 | 6.11 | 10.11 | 51.9 |
| 2.5 | 20 | 95 | 4 | 47.5 | 7.97 | 11.97 | 61.5 |

Suzuki and Yasuhara, Soils and Foundations, 2007

11-04-2023

Record of Pore Water Pressure, Settlement & N-Value



| N-Value Before & After Installation of PVDs (Ch: 42.44) | | | | | | | |
|--|------------------------------|---------|----------|--|--|--|--|
| Depth | Description | Old | New | | | | |
| from | of the Soil | Bank | Bank | | | | |
| OGL | | (May | (11 Jan | | | | |
| | | 2014) | 2016) | | | | |
| 2 | Soft , deep, grey | 4 | 9 | | | | |
| 3 | clayey soil | 4 | 15 | | | | |
| 4.5 | Medium, deep, | | 16 | | | | |
| 6 | grey clayey silty soil | 4 | 11 | | | | |
| 7 | Medium, deep, | 7 | 16 | | | | |
| 9 | grey clay silty sand soil | 6 | 25 | | | | |
| 11 | Medium dense | 4 | 28 | | | | |
| 12.5 | silty sand | 3 | 29 | | | | |
| 14.5 | Medium to dense | 6 | 36 | | | | |
| 16 | sandy soil | 66 | 72 | | | | |
| 17.5 | Very dense sandy soil | 100 | 100 | | | | |
| N-Valu | e After 51 days of P | VD inst | allation | | | | |

11-04-2023

135

Retrofitting of Railway Station Building

USE OF MODERN RETROFITTING TECHNIQUES IN UDAIPUR STATION BUILDING OF AGARTALA-SABROOM NEW LINE PROJECT OF N.F.RAILWAY

By: Harpal Singh, Chief Engineer/Con-8/Maligaon,

B.N.Bhaskar, Deputy Chief Engineer/Con/Agartala,

Koteshwar Ponnala, Asstt. Executive Engineer/Udaipur



http://ipweindia.org.in/index.php/books-publications/technical-papers/10-publications https://drive.google.com/file/d/1b4Xu7IIM6ZykaMArHBwnIIFzDZOqLLaH/view?usp=sharing









11-04-2023 IDRRR, MZV, 2023



11-04-2023

Heritage Railway Station, Udaipur, Agartala

• Application of preloading and PVD for developing of railway yard in a ditch marshland







11-04-2023

IDRRR, MZU, 2023



11-04-2023

